

# POSITIONNEURS MAGNÉTIQUES

Pour plus de confort lors de vos soudures



# Des positionneurs magnétiques pour le confort du soudeur

# **MAGNETIC P 15.90**

• 🜣 Angle : 60° & 90°

• 👰 15 kg

• 🚓 100 x 73 x 12

• x2

047044







### **MAGNETIC P 16.90**

• \$\sqrt{\text{Angle}} \text{ Angle} : 45\sqrt{\text{,}} 90\sqrt{\text{ & 135\sqrt{\text{o}}}}


• № 16 kg

• 🚓 45 x 32 x 28

• 📆











# **MAGNETIC P 19.90**

• 🜣 Angle : 45°, 90° & 135°

• 🔐 19 kg

• 🚓 156 x 102 x 20

• x1

044203











# **MAGNETIC P 20.180**

- 💸 0 > 180°
- 👰 20 kg
- 🚓 204 x 86 x 28

• x1

044302



# **MAGNETIC D50.90 DUAL**

**1** 

- 🜣 Angle : 90°
- **1** 50 kg
- 🚓 148 x 148 x 38



047051





Switchable

#### **MAGNETIC D36.90**

Switchable


- \$\sigma\$ Angle: 45°, 90° & 135°
- 🔐 30 kg
- 🕁 111 x 95 x 25
- x1

044197











#### MAGNETIC D50.90 Switchable

- 🜣 Angle: 90°
- № 50 kg
- 🚓 71 x 60 x 48
- x1

047075





# MAGNETIC D70.90 M Switchable

- 🜣 Angle : 90°
- ♣ 70 kg ♣ 48 x 32 x 70

047068



# **MAGNETIC D70.120M**

Switchable

- \$\times \text{Angle: 45°, 60°, 75°, 90°, 105° & 135°}

• x1


047082















#### MAGNETIC D70.135M

Switchable

• 🜣 Angle : 45°, 75°, 90°, 105° & 135°

- 🔐 70 kg
- ∰ 99 x 55 x 80
- x1



#### 047099















Fax: (+33) 2 43 68 35 21 www.gys.fr / E-mail: contact@gys.fr